xerox™

Xerox FD70 Scanner Assembly

Device Type   Scanner
ErP Equipment Type: Other Networked Equipment

POWER SUPPLY
Voltage (Volts)   100-240 vac
Output Rating (Watts)   48

POWER MODE

	Power (Watts)	Default Period (Minutes)
Ready/Standby	7.77	0
Sleep 1	0.66	15
Plugged In Off	0.12	Not applicable
Networked Standby - All ports	0.66	Not applicable
Networked Standby - USB	0.66	Not applicable

GUIDANCE – WIRELESS PORT (NOT APPLICABLE)

1. Deactivation

- Not applicable

2. Activation

- Not applicable

For more information about Xerox environmental programs in *North America,* refer to: www.xerox.com/Environment
For more information about Xerox environmental programs in *Europe,* refer to: www.xerox.com/environment_europe